



PIEDMONT ENVIRONMENTAL SERVICES, INC.

P.O. Box 8861
Greensboro, NC 27419
(919) 668-4821

RECEIVED
N.C. Dept. NRCD

MAR 20 1990

Winston-Salem
Regional Office

March 16, 1990

Mr. Andrew Raring
North Carolina Department of Natural
Resources and Community Development
8025 North Point Blvd., Suite 100
Winston-Salem, NC 27106

RE: Piedmont Optical Co. - 3008 Executive Drive
Greensboro, NC

Dear Mr. Raring,

On February 26, 1990 Piedmont Environmental Services removed one (1)
1000 gallon fuel oil tank from the above location. Soil test were
taken and attached is the results of those tests.

The tank removed did have some leakage or spillage from overfill.
The tank was disposed of at Safeway Tanks, Colfax, NC. We hope to
help Piedmont Optical with their clean up after notification from
your office.

If any further information is needed please let us know.

Sincerely,



Bill Stewart

attachment

cc: Mr. Richard Turk - Piedmont Optical

**GUILFORD LABORATORIES, INC.**

P.O. Box 9735/Plaza Station/Greensboro, N.C. 27408

RECEIVED
N.C. Dept. NRCD

MAR 20 1990

Winston-Salem
Regional Office

March 8, 1990

REPORT OF ANALYSIS

JOB #: PEI00226

CUSTOMER: Piedmont Enviromental


ATTN: Bill Stewart

P.O. #: Piedmont Optical

SAMPLE: # 1755 TEST #1 E END HEATING OIL
1756 TEST #2 W END HEATING OILRESULTS

	<u>1755</u>	<u>1756</u>
Total Petroleum Hydrocarbons (ppm) by Method 3550	59	(10)

Guilford Laboratories, Inc.


J. A. Rayburn

Piedmont Optical Company

3008 Executive Drive
277-8146



GREENSBORO

SOUTH Elm Street

INDUSTRIAL Ave

3008

225'

EXECUTIVE DR

One (1) 1000 gallon
Fuel Oil - Individual
Test taken 2' below
tank at each end